

Rio Tinto

Kennecott Utah Copper LLC
4700 Daybreak Parkway
South Jordan, Utah 84095
801-569-7887 (o)
801-569-6147 (f)

Brian G. Vinton, P.G.
Environment, Principal Advisor Water Quality

MO350002
rec'd 6-12-13

April 30, 2013

Mr and Mrs Boyd Dansie
7041 West 13090 South
Herriman, Utah 84096


Dear Mr and Mrs Boyd Dansie,

Soil characterization work was conducted on your property from October 13 through December 13, 2012 by Anderson Engineering Company, Inc. This detailed soil survey focused on lead and arsenic concentration from ground surface through 18 inches below surface.

Transmitted with this letter is the final report which includes a summary of the work completed. The information includes data tables and maps showing the lead and arsenic concentrations along with the quality assurance for the data and field notes.

I will be available to go over the information with you at your convenience.

Sincerely,



Brian Vinton
Principal Advisor, Water Quality
Kennecott Utah Copper LLC

Cc: Paul Baker, DOGM w/o attachments
Doug Bacon, UDERR w/o attachments